





- 1. Attach the 2 desk legs: Place the desk face down on a non-abrasive surface. Use (12) #14 black screws to screw into pre-drilled 5mm holes.
- Note: There are 2 sets of mounting holes (see illustration below). The outer position is the normal placement. The inner sets are used with a Drawer Bank or Equipment Rack.
- 2. Attach the wire chase to the underside of the desk where desired using the #8-10X3/4" Screws (12). There are no pre-drilled holes, but the screws are self tapping.
- 3. Stand the desk up on its legs. Attach the Connecting Bolts to the desk top and underside of the monitor bridge using a #3 phillips head or flat blade screw driver.
- 5. If using the Rack Rail, attach it to the Risers using the #10 x 1/2" screws. Risers are pre-drilled.
- 4. Attach the risers to the desk top. Be sure the alignment "arrow" molded into the cam is pointing to the adjacent edge with a hole. Place risers over the connceting bolts. Using a 6mm allen wrench, tighten the cams.
- 5. Place the monitor bridge on the risers. Tighten the cams, again using the 6mm allen wrench.
- 7. Attach the Leg Wire Chase to one of the legs. Remove adhesive strips and place where desired.




















C72 **Assembly Instructions**



martinandziegler.com P503-266-7660 F503-266-7661 421 NE 3rd Ave Canby, OR 97013

Date	2013		Rev.	
Scale	NTS		Sheet	1 of 1
Drawn	by			
Approv	/ed			Date